




Operation Manual

eYc SD03 Integrated Indicator




eYc SD03





Note 1.

- A) Readout decimal point that you set.
- B) Adjustment range: -1999 ... 9999.



- C) Default:
4mA corresponding 400
20mA corresponding 2000

Note 2.

- A) Adjustment of readout's response time. 0.5s/ Unit.
- B) The range of response time: (0s ... 20s)
- C) Default: 0s (s: second)


Note 3.

To save, please press ►+▲ at the same time after you finished setting, and then it will skip to next parameter.


Note 4.

If you didn't press any key over 20s during setting, it will exit setting program and return to main manual without save.

Diagram



DIN43650 Connector



M12 Connector

Accurate | Professional | Stable

Temperature and Humidity / Dew Point / Air Velocity / Flow / Pressure

Measuring Specialist



Tel.: 886-2-8221-2471
Web : www.eyc-tech.com
e-mail : info@eyc-tech.com